

imagemaster
printing products

imagemaster
poly tape inks

imagemaster
pvc tape inks

imagemaster
release coatings

imagemaster
adhesive deadener

imagemaster
specialty additives

imagemaster
plate mount tape

imagemaster
printing blankets

imagemaster
uv printing inks

imagemaster
printing products

PPT SERIES TAPE INKS

Specially formulated ink system for treated (BOPP) polypropylene tapes that can also be used on a wide variety of treated acrylic's, polyesters, flat back, masking, gaffer, and paper tapes. In most cases you will also be able to reverse print these inks on the adhesive side as well.

Printing recommendations

- Use inks and tape at room temperature.
- Mix only what ink is needed. Do not return leftover ink to original container.
- Use heat if required only before printing. Once printed, try to cool as much as possible with airflow.
- Check the squeeze (between plate and impression) to ensure even ink laydown.
- Compare printed color to standard. If color too strong add more solvent.
- Add maximum cooling air circulation before rewind.
- Make sure the tension of the rewind is at the lowest possible tension for good rewind.
- Drum temperature should be cold or lukewarm, never hot.
- Good airflow (without heat) fully directed on tape (after printing) is essential for proper drying.
- If picking occurs, check impression for too much ink transfer (especially on edges of print) and make adjustments. Increasing solvent may also help.
- Contact your representative for further recommendations.

Recommended Solvents

- Reducing solvent must be added to the PPT - Series Inks. Between 15% and 30%* of PPT-9540B blending solvent should be added to well stirred / shaken ink to ensure the best print results.
(*dependant on anilox roller used and desired color strength)
- As a starting point, add 15% (weight / weight) solvent to the ink. (Note: Ink should be well mixed before adding solvent). Please add measured amounts of solvent to the ink in a separate metal container rather than in the ink-tray. Mix only sufficient quantities to fill ink-tray once. Record quantity added.

Note

Solvent selection should be the fastest combination consistent with clean printing and with a focus on the press capacity to dry the product. This procedure will insure a low level of solvent retention and insure consistent non-blocking properties. The operator should pay attention to the viscosity of the ink in the fountain and may be required to add additional solvent during longer print runs.

Clean Up

Use reducing solvents (normal isopropyl alcohols)

Precautions

Flammable liquid. Keep all containers sealed when not in use. Store in approved area for flammable liquids between 15°C and 30°C. Mix all containers prior to use. Review MSDS before using.

The information and recommendations in this publication are to the best of our knowledge reliable. Suggestions made concerning uses or applications are only the opinion of Image Group and users should make their own tests to determine the suitability of these products for their own particular purposes. However, because of numerous factors affecting results, Image Group makes no warranty of any kind, express or implied, including those of merchantability and fitness for particular purpose, other than that the material conforms to its applicable current Standard Specifications. Statements herein, therefore, should not be construed as representations or warranties. The responsibility of Image Group shall, in no event, be liable for special, incidental or consequential damages, including loss of profits. Statements concerning the use of the products or formulation described herein are not to be construed as recommending the infringement of any patent and seller assumes no liability for infringement arising out of any such use.



IMAGE PRINTING PRODUCTS INTERNATIONAL

2284 Speers Road, Oakville, Ontario L6L 2X8

Phone: 905/825-5600 Fax: 905/825-8833

1-800-561-4657

www.imagegrp.com info@imagegrp.com

image
GROUP
OF COMPANIES